
























"Ci-Murat"

	Soldador 30 w. p. lapiz		
CIMU0001	Soldador 40 w. p. lapiz		
CIMU0002	Soldador 45 w.		
CIMU0003	Soldador 60 w. p. lapiz		
CIMU0004	Soldador 60 w.		
CIMU0005	Soldador 75 w.		
CIMU0006	Soldador 100 w.		
CIMU0007	Soldador 160 w		
CIMU0008	Soldador 200 w.		
CIMU0009	Punta de cobre 30 w. p. lapiz		
CIMU0010	Punta de cobre 40 w. p. lapiz		
CIMU0011	Punta de cobre 45 w.		
CIMU0012	Punta e cobre 60 w. p. lapiz		
CIMU0013	Punta de cobre 60 w.		
CIMU0014	Punta de cobre 75 w.		
CIMU0015	Punta de cobre 100 w.		
CIMU0016	Punta de cobre 160 w.		
CIMU0017	Punta de cobre 200 w.		
CIMU0018	Resistencia 30 w.		
CIMU0020	Resistencia 40 w.		
CIMU0021	Resistencia 45 w.		
CIMU0022	Resistencia 60 w.		
CIMU0023	Resistencia 75 w.		

CIMU0024 Resistencia 100 w.



CIMU0025 Resistencia 160 w.



CIMU0026 Resistencia 200 w.



CIMU0027